



1085 Texan Trail
 Grapevine, Texas 76051
 817-424-0383
www.tkavation.com



TPE 331 ENGINE INFORMATION SHEET

ENGINE TYPE: TPE 331-10R-511C

ENGINE SERIAL NUMBER: P-37405C

TSN: 16015.7 TSO: 961.4
CSN: 20686 CSO: 1107
TBO 5000

Life Limited information

| Part | Part number | Serial number | CSN | CR | Remarks |
|--------------------------|-------------|---------------|------------|-------|---------|
| 1 st Twheel | 3108164-2 | 070322900190 | 1107 | 18893 | |
| 2 nd Twheel | 3102106-10 | 030134501231 | 3407 | 11593 | |
| 3 rd Twheel | 3102655-2 | 070134505212 | 1107 | 4893 | |
| 1st Seal plate | 3102484-1 | 070350107201 | 1107 | 18893 | |
| 1 st Impeller | 3108182-1 | 060350108039 | 1107 | 28893 | |
| 2 nd impeller | 893482-3 | 2-03501-458 | N/A | | |
| | | | | | |
| Fuel Control | 897801-17 | 1486783 | TSO: 961.4 | TR: | |
| Fuel Pump | 897390-8 | P-199C | TSO: 543.9 | TR: | |
| Prop Pitch Control | 895481-22 | P-3055C | TSO: 961.4 | TR: | |
| Prop Governor | 897751-1 | P-329C | TSO: 961.4 | TR: | |
| | | | | | |
| | | | | | |
| | | | | | |

Comments:

Combustion liner 3107173-1

Engine long-term preserved in April 2016.

Repaired by CD Aviation in April 2016 for a carbon seal leak. Completed Re-compensation Test and Lebow Test.