



1085 Texan Trail
 Grapevine, Texas 76051
 817-424-0383
www.tkavation.com



TPE 331 ENGINE INFORMATION SHEET

ENGINE TYPE: TPE331-10T-515K

ENGINE SERIAL NUMBER: P-79613

TSN: 5480.4

CSN: 6764

TSO: 237.6 Aug 9 2001

CSO: 249

5000 TBO

Engine converted & overhauled by Garrett Aviation in August 2001 at

TSN: 5242.8 & CSN: 6515.

Landmark Aviation performed DERB repair in October 2007 at TSO: 20.8 hours.

Life Limited information

Part	Part number	Serial number	CSN	CR	Remarks
1 st Twheel	3101520-3	000322900181	249	19751	
2 nd Twheel	3102106-10	010134503005	249	14751	
3 rd Twheel	3102655-2	000134513995	249	5751	
Seal Plate	3102484-1	000350101946	249	19751	
1 st impeller	3108182-2	000350103406	249	29751	
2 nd impeller	893482-4	4-03501-2105		N/A	
Comp bearing	3101405-1	070233005366	TSO: 229	4771 TR	
Torque sensor	3101726-3	P7073	TSO: 249	4751 TR	
FCU	893528-32	325654	TSO: 228.2	4771.8 TR	
Fuel pump	897385-1	MX330461	TSO: 249	4751 TR	
Prop governor	895490-11	1475502	TSO: 217.4	4782.6 TR	

Removal date: 8/4/2008

Preserved by DAO Expires 11/2018

5000 TBO